| Date | Source | Gallons | Tons | Field |
|---|---|---|---|---|
| 1/8/2021 | Heifer Barn | 15000 | | R11 |
| 1/19/2021 | Heifer Barn | 4,500.00 | | R 11 |
| 1/19/2021 | Heifer Barn | 22,500.00 | | R 11 |
| 1/21/2021 | P1 | 51,000.00 | | E 3 |
| 1/22/2021 | P1 | 25,500.00 | | E 3 |
| 1/25/2021 | P1 | 76,500.00 | | E-3 |
| 1/26/2021 | P1 | 31,500.00 | | K1 |
| 1/28/2021 | P1 | 58,500.00 | | K1 |
| 2/4/2021 | Heifer Barn | 20000.00 | | Q11 |
| 3/10/2021 | Heifer Barn | 25,000.00 | | R11 |
| 3/10/2021 | Dairy Barn | 40,000.00 | | K1 |
| 3/11/2021 | Dairy Barn | 72,000.00 | | E3 |
| 3/11/2021 | Dairy Barn | 16,000.00 | | K1 |
| 3/12/2021 | Dairy Barn | 32,000.00 | | N1 |
| 3/12/2021 | Dairy Barn | 32,000.00 | | O1 |
| 3/13/2021 | Dairy Barn | 24,000.00 | | O1 |
| 3/13/2021 | Dairy Barn | 40,000.00 | | N1 |
| 3/14/2021 | Dairy Barn | 40,000.00 | | O2 |
| 3/16/2021 | Dairy Barn | 36,000.00 | | Sugar 2 |
| 3/17/2021 | Dairy Barn | 36,000.00 | | Sugar 3 |
| 3/22/2021 | Dairy Barn | 40,000.00 | | F 19 |
| 3/22/2021 | Dairy Barn | 72,000.00 | | Glosik |
| 3/23/2021 | Dairy Barn | 112,000.00 | | Eagle Valley |
| 3/24/2021 | Dairy Barn | 120,000.00 | | Eagle Valley |
| 3/25/2021 | Dairy Barn | 72,000.00 | | Eagle Valley 2&3 |
| 3/26/2021 | Dairy Barn | 112,000.00 | | Eagle Valley 2&3 |
| 3/27/2021 | Dairy Barn | 56,000.00 | | Eagle Valley 2&3 |
| 3/29/2021 | P2 | 48,000.00 | | ST 7 |
| 3/30/2021 | P2 | 64,000.00 | | St6 |
| 3/31/2021 | P2 | 64,000.00 | | St5 |
| 4/5/2021 | P2 | 90,000.00 | | A 12 S |
| 4/6/2021 | P2 | 72,000.00 | | ST 5 |
| 4/7/2021 | P2 | 40,000.00 | | ST 6 |

| | | | | |
|---|---|---|---|---|
| 4/8/2021 | P2 | 40,000.00 | | ST5 |
| 4/9/2021 | P2 | 40,000.00 | | ST6 |
| 4/10/2021 | P2 | 40,500.00 | | ST 6 |
| 4/26/2021 | P2 | 25,000.00 | | ST6 |
| 4/26/2021 | P2 | 25,000.00 | | St5 |
| 4/27/2021 | P2 | 25,000.00 | | St5 |
| 4/28/2021 | P2 | 25,000.00 | | St6 |
| 5/11/2021 | P1 | 34,000.00 | | EV 2 |
| 5/11/2021 | P1 | 32,000.00 | | EV 3 |
| 5/11/2021 | P1 | 36000.00 | | EV 2 |
| 5/13/2021 | P1 | 48000.00 | | EV 3 |
| 5/14/2021 | P1 | 44000.00 | | EV 2 |
| 5/17/2021 | Dairy | 50,000.00 | | EV |
| 5/18/2021 | Dairy | 50,000.00 | | Z1a |
| 5/19/2021 | Dairy | 50,000.00 | | Z1a |
| 5/20/2021 | Dairy | 24,000.00 | | Z1a |
| 5/20/2021 | Dairy | 88,000.00 | | Tucker 5 |
| 5/21/2021 | Dairy | 45,000.00 | | Tucker 1 |
| 5/26/2021 | P2 | 31,500.00 | | ST 8 |
| 5/26/2021 | P2 | 37,500.00 | | ST 5 |
| 6/1/2021 | P2 | 52,000.00 | | ST 6 |
| 6/1/2021 | P2 | 54,000.00 | | ST 8 |
| 6/2/2021 | P2 | 4,000.00 | | ST 6 |
| 6/3/2021 | P2 | 47,500.00 | | ST 4 |
| 6/4/2021 | P2 | 44,000.00 | | ST4 |
| 6/7/2021 | P2 | 24000.00 | | ST4 |
| 6/7/2021 | P2 | 3500.00 | | no field |
| 6/7/2021 | P2 | 4000.00 | | no field |
| 6/9/2021 | P2 | 36000.00 | | St4 |
| 6/11/2021 | P2 | 16000.00 | | St4 |
| 6/14/2021 | P2 | 40,000.00 | | ST 4 |
| 6/15/2021 | P2 | 40,000.00 | | ST 4 |
| 6/16/2021 | P2 | 40,000.00 | | ST 4 |
| 6/17/2021 | P2 | 50,000.00 | | ST 4 |

| | | | | |
|---|---|---|---|---|
| 6/18/2021 | P2 | 50,000.00 | | ST 4 |
| 6/21/2021 | Heifer barn | 18000.00 | | C11 |
| 6/28/2021 | P1 | 25,500.00 | | F13 |
| 6/28/2021 | P1 | 25,500.00 | | F 13 |
| 6/29/2021 | P1 | 25,500.00 | | F 13 |
| 6/29/2021 | P1 | 7,500.00 | | M3 |
| 6/30/2021 | P1 | 7,500.00 | | M3 |
| 6/30/2021 | P1 | 13,500.00 | | E4 |
| 6/30/2021 | P1 | 32,000.00 | | E1 |
| 6/30/2021 | P1 | 32,000.00 | | I1 |
| 6/30/2021 | P1 | 16,000.00 | | H 2A |
| 6/30/2021 | P1 | 21,000.00 | | M3 |
| 7/1/2021 | P1 | 22,500.00 | | E4 |
| 7/2/2021 | Heifer Barn | 11000.00 | | c11 |
| 8/3/2021 | P1 | 25000 | | P1A |
| 8/4/2021 | p1 | 25000 | | P1A |
| 8/5/2021 | Biosolids storage | | 10.00 | P1a |
| 8/6/2021 | P1 | 25000 | | P1a |
| 8/9/2021 | P1 | 15000 | | Glosick 11 |
| 8/10/2021 | P1 | 15000 | | Glosick 10A |
| 8/11/2021 | P1 | 15000 | | Glsoick 10B |
| 8/12/2021 | P2 | 15000 | | M6 |
| 8/13/2021 | P2 | 15000 | | M6 |
| 8/16/2021 | P2 | 50000 | | P1A |
| 8/17/2021 | Dairy Barn | 20000 | | P1A |
| 8/20/2021 | Dairy Barn | 20000 | | P1A |
| 8/23/2021 | Dairy Barn | 20000 | | P1A |
| 8/24/2021 | P2 | 122000 | | m3 |
| 8/25/2021 | P2 | 80000 | | m2 |
| 8/26/2021 | P2 | 80000 | | J1 |
| 8/27/2021 | P1 | 80000 | | J1 |
| 10/13/2021 | P2 | 25000 | | M5 |
| 10/14/2021 | P2 | 25000 | | M5 |
| 10/15/2021 | P2 | 25000 | | M5 |

| | | | | |
|---|---|---|---|---|
| 11/6/2021 | P2 | 25000 | | A12S |
| 11/7/2021 | P2 | 25000 | | A12S |
| 11/8/2021 | P2 | 15000 | | A12S |
| 11/10/2021 | p2 | 140000 | | k1 |
| 11/11/2021 | P2 | 187000 | | k1 |
| 11/15/2021 | P2 | 125000 | | H3 |
| 11/16/2021 | P2 | 125000 | | H3 |
| 11/21/2021 | P1 | 99,200.00 | | F2 |
| 11/22/2021 | P1 | 86,800.00 | | E3 |
| 11/23/2021 | P1 | 62,000.00 | | F19 |
| 11/23/2021 | P1 | 93,000.00 | | F15 |
| 11/24/2021 | P1 | 24,800.00 | | F11 |
| 11/24/2021 | P1 | 111,600.00 | | F10 B |
| 11/26/2021 | P1 | 49,600.00 | | F4 |
| 12/1/2021 | P1 | 83,200.00 | | J 2 |
| 12/1/2021 | P1 | 51,200.00 | | J4 |
| 12/2/2021 | Dairy | 89,600.00 | | A 7 |
| 12/2/2021 | Dairy | 6,400.00 | | A7 |
| 12/2/2021 | Dairy | 12,800.00 | | W9 |
| 12/9/2021 | Dairy | 168,000.00 | | Glosick 11,12,13, |
| 12/10/2021 | Dairy | 88,000.00 | | L 2 |
| 12/10/2021 | Dairy | 48,000.00 | | Glossick |
| 12/10/2021 | Dairy | 8,000.00 | | Sugar |
| 12/10/2021 | Dairy | 96,000.00 | | L 1 |
| 12/13/2021 | Dairy | 128,000.00 | | W9 |
| 12/13/2021 | Dairy | 8,000.00 | | W1 |
| 12/13/2021 | Dairy | 104,000.00 | | J2 |
| 12/14/2021 | P2 | 120,000.00 | | N 1 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

| | | | | |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |

| | | | | |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |

| | | | | |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |

| Machine | Operator | |
|---|---|---|
| 9105 | Ks | |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| KS | Ks | Top Spread |
| KS | Ks | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | KS | Top Spread |
| 9105 | Ks | Incorporated |
| 9105 | KS | Incorporated |
| 9105 | KS | Incorporated |
| 9105 | DB | Incorporated |
| 9105 | MV | Incorporated |
| 9105 | MV | Incorporated |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 9105 | MV | Incorporated | | | | | | | | |
| 9105 | MV | Incorporated | | | | | | | | |
| 9105 | DB | Incorporated | | | | | | | | |
| 9105 | MV | Incorporated | | | | | | | | |
| 9105 | MV | Incorporated | | | | | | | | |
| 9105 | MV | Incorporated | | | | | | | | |
| 9105 | MV | Incorporated | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| Quad | KS | Top Spread | | | | | | | | |
| 9105 | KS | Incorporated | | | | | | | | |
| 9105 | KS | Incorporated | | | | | | | | |
| 9105 | KS | Incorporated | | | | | | | | |
| 9105 | KS | Incorporated | | | | | | | | |
| 9105 | KS | Incorporated | | | | | | | | |
| 9105 | KS | Incorporated | | | | | | | | |
| Quad | KS | Incorporated | | | | | | | | |
| Quad | KS | Incorporated | | | | | | | | |
| | | invloved in accident went over the bank on Shauger Road | | | | | | | | |
| | | The remainder of the material on the trailer was pumped onto another trailer and dumped back into P2 | | | | | | | | |
| Quad | Ks | Incorporated | | | | | | | | |
| Quad | Ks | Incorporated | | | | | | | | |
| Quad | KS | Incorporated | | | | | | | | |
| Quad | KS | Incorporated | | | | | | | | |
| Quad | KS | Incorporated | | | | | | | | |
| Quad | KS | Incorporated | | | | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| Quad | KS | Incorporated | | | | | | | | |
| 9105 | KS | top spread | | | | | | | | |
| spread trlr | DB | top spread | | | | | | | | |
| spread trlr | DB | top spread | | | | | | | | |
| spread trlr | DB | top spread | | | | | | | | |
| 9105 | KS | top spread | | | | | | | | |
| spread trlr | DB | top spread | | | | | | | | |
| 9105 | KS | top spread | | | | | | | | |
| spread trlr | DB | top spead | | | | | | | | |
| spread trlr | DB | top spread | | | | | | | | |
| spread trlr | DB | top spread | | | | | | | | |
| 9105 | KS | top spread | | | | | | | | |
| 9105 | KS | top spread | | | | | | | | |
| 9105 | KS | Top Spread | | | | | | | | |
| 9105 | ks | | | | | | | | | |
| 9105 | ks | | | | | | | | | |
| dry spreader | LD | | | | | | | | | |
| 9105 | Ks | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | Ks | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | Ks | | | | | | | | | |
| 9105 | | | | | | | | | | |
| custom spread | | | | | | | | | | |
| custom spread | | | | | | | | | | |
| custom spread | | | | | | | | | | |
| custom spread | | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | Ks | | | | | | | | | |
| 9105 | KS | | | | | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 9105 | Ks | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| 9105 | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| Quad | KS | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

| **Storage Inspection** | | | | | |
|---|---|---|---|---|---|
| 2020 | Date | Level | Initials | Condition | Corrective Action |
| | | | | | |
| P1 Effluent | 1/4/2021 | 6 inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 1/11/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 1/18/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 1/25/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 2/1/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |

| | | | | | |
|---|---|---|---|---|---|
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 2/8/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 2/15/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 2/22/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 3/1/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 3/8/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |

| | | | | | |
|---|---|---|---|---|---|
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 60 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 3/15/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | on the mark | | | pumping P2 into P3 |
| P3 Corner Pond | | 13 inches below the mark | | | |
| P4 Irragation Pond | | 14 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 6 inches above the mark | | | spreading out of dairy stor |
| | | | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 3/22/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | 4 inches below the mark | | | |
| P3 Corner Pond | | 10 inches below the mark | | | |
| P4 Irragation Pond | | 10 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 4 inches above the mark | | | spreading out of dairy stor |
| | | | | | |
| | | | | | |
| P1 Effluent | 3/29/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | 4 inches below the mark | | | |
| P3 Corner Pond | | 10 inches below the mark | | | |
| P4 Irragation Pond | | 10 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 4/5/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | 5 inches below the mark | | | |
| P3 Corner Pond | | 10 inches below the mark | | | |
| P4 Irragation Pond | | 10 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 4/12/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | 5 inches below the mark | | | |

| | | | |
|---|---|---|---|
| P3 Corner Pond | | 10 inches below the mark | |
| P4 Irragation Pond | | 10 inches below the mark | |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| | | | |
| P1 Effluent | 4/19/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | 5 inches below the mark | |
| P3 Corner Pond | | 10 inches below the mark | |
| P4 Irragation Pond | | 10 inches below the mark | |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 4/26/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | 5 inches below the mark | |
| P3 Corner Pond | | 10 inches below the mark | |
| P4 Irragation Pond | | 10 inches below the mark | |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 5/3/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | 5 inches below the mark | pumping P4 into P2 until it |
| P3 Corner Pond | | 10 inches below the mark | pumping P3 to P4 |
| P4 Irragation Pond | | 10 inches below the mark | pumping P4 to P2 |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 5/10/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | 5 inches below the mark | |
| P3 Corner Pond | | 10 inches below the mark | |
| P4 Irragation Pond | | 10 inches below the mark | |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| | | | |
| P1 Effluent | 5/17/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | 5 inches below the mark | |

| | | | |
|---|---|---|---|
| P3 Corner Pond | | 10 inches below the mark | |
| P4 Irragation Pond | | on the mark | |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| | | | |
| P1 Effluent | 5/24/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | on the mark | spreading out of P2 |
| P3 Corner Pond | | 10 inches below the mark | |
| P4 Irragation Pond | | on the mark | p4 will be pumped to P2 or |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 6/1/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | 1 inch below the mark | |
| P3 Corner Pond | | 10 inches below the mark | |
| P4 Irragation Pond | | on the mark | |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 6/7/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | 5 inch below the mark | |
| P3 Corner Pond | | 10 inches below the mark | |
| P4 Irragation Pond | | on the mark | |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 6/14/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | 6 inch below the mark | |
| P3 Corner Pond | | 10 inches below the mark | |
| P4 Irragation Pond | | on the mark | |
| Dairy Storage | | 48 inches below the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 6/21/2021 | 6 inches inches below the mark | |
| P2 spread Pond | | 26 inch below the mark | |
| P3 Corner Pond | | 10 inches below the mark | |

| | | | | | |
|---|---|---|---|---|---|
| P4 Irragation Pond | | 12 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 6/28/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | 26 inch below the mark | | | |
| P3 Corner Pond | | 10 inches below the mark | | | |
| P4 Irragation Pond | | 12 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 7/5/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | 26 inch below the mark | | | |
| P3 Corner Pond | | 10 inches below the mark | | | |
| P4 Irragation Pond | | 12 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 7/12/2021 | 6 inches inches below the mark | | | |
| P2 spread Pond | | 26 inch below the mark | | | |
| P3 Corner Pond | | 10 inches below the mark | | | |
| P4 Irragation Pond | | 12 inches below the mark | | | |
| Dairy Storage | | 48 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 7/19/2021 | on the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | 3 inches below the mark | | | |
| P4 Irragation Pond | | on the mark | | | |
| Dairy Storage | | on the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 7/26/2021 | on the mark | | | |
| P2 spread Pond | | on the mark | | | |

| | | | | | |
|---|---|---|---|---|---|
| P3 Corner Pond | | 3 inches below the mark | | | |
| P4 Irragation Pond | | on the mark | | | |
| Dairy Storage | | on the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 8/2/2021 | above the mark | | | |
| P2 spread Pond | | above the mark | | | |
| P3 Corner Pond | | above the mark | | | |
| P4 Irragation Pond | | above the mark | | | |
| Dairy Storage | | above the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 8/9/2021 | above the mark | | | |
| P2 spread Pond | | above the mark | | | |
| P3 Corner Pond | | above the mark | | | |
| P4 Irragation Pond | | above the mark | | | |
| Dairy Storage | | above the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 8/16/2021 | 6 inches below the mark | | | |
| P2 spread Pond | | on the mark 8/17/2021 3pm | | | |
| P3 Corner Pond | | above the mark | | | |
| P4 Irragation Pond | | on the mark | | | |
| Dairy Storage | | above the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 8/23/2021 | 1 inch below the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | above the mark | | | |
| P4 Irragation Pond | | on the mark | | | |
| Dairy Storage | | on the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 8/30/2021 | 12 inches below the mark | | | |
| P2 spread Pond | | 12 inches below the mark | | | |
| P3 Corner Pond | | above the mark | | | |

| | | | |
|---|---|---|---|
| P4 Irragation Pond | | 3 inches below the mark | |
| Dairy Storage | | on the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 9/7/2021 | 12 inches below the mark | |
| P2 spread Pond | | 12 inches below the mark | |
| P3 Corner Pond | | above the mark | |
| P4 Irragation Pond | | 3 inches below the mark | |
| Dairy Storage | | on the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 9/13/2021 | 12 inches below the mark | |
| P2 spread Pond | | 12 inches below the mark | |
| P3 Corner Pond | | above the mark | |
| P4 Irragation Pond | | 3 inches below the mark | |
| Dairy Storage | | on the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| | | | |
| P1 Effluent | 9/20/2021 | 12 inches below the mark | |
| P2 spread Pond | | 12 inches below the mark | |
| P3 Corner Pond | | above the mark | |
| P4 Irragation Pond | | 3 inches below the mark | |
| Dairy Storage | | on the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| | | | |
| P1 Effluent | 9/27/2021 | 12 inches below the mark | |
| P2 spread Pond | | 12 inches below the mark | |
| P3 Corner Pond | | above the mark | |
| P4 Irragation Pond | | 3 inches below the mark | |
| Dairy Storage | | on the mark | |
| B4 Mix Tank | | 60 inches below the mark | |
| B1 Reception Pit | | 50 inches below the mark | |
| Heifer Storage | | 40 inches below the mark | |
| | | | |
| P1 Effluent | 10/4/2021 | 12 inches below the mark | |
| P2 spread Pond | | 12 inches below the mark | |
| P3 Corner Pond | | above the mark | |

| | | | | | |
|---|---|---|---|---|---|
| P4 Irragation Pond | | 3 inches below the mark | | | |
| Dairy Storage | | on the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 10/12/2021 | on the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | on the mark | | | |
| P4 Irragation Pond | | 3 inches below the mark | | | |
| Dairy Storage | | on the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 10/18/2021 | on the mark | | | |
| P2 spread Pond | | 2 inches below the mark | | | |
| P3 Corner Pond | | on the mark | | | |
| P4 Irragation Pond | | 3 inches below the mark | | | |
| Dairy Storage | | on the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 10/25/2021 | on the mark | | | |
| P2 spread Pond | | on the mark | | | |
| P3 Corner Pond | | on the mark | | | |
| P4 Irragation Pond | | on the mark | | | |
| Dairy Storage | | on the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | 40 inches below the mark | | | |
| | | | | | |
| P1 Effluent | 11/1/2021 | full | | | |
| P2 spread Pond | | full | | | |
| P3 Corner Pond | | full | | | |
| P4 Irragation Pond | | full | | | |
| Dairy Storage | | full | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | empty | | | |
| | | | | | |
| P1 Effluent | 11/8/2021 | 6 inches above the mark | | | |
| P2 spread Pond | | 6 inches above the mark | | | |
| P3 Corner Pond | | 6inches above the mark | | | |
| P4 Irragation Pond | | 6 inches above the mark | | | |

| | | | | | |
|---|---|---|---|---|---|
| Dairy Storage | | 1 foot above the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | empty | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 11/15/2021 | 6 inches above the mark | | | |
| P2 spread Pond | | 20 inches below the mark | | | |
| P3 Corner Pond | | 3 inches above the mark | | | |
| P4 Irragation Pond | | 6 inches above the mark | | | |
| Dairy Storage | | 1 foot above the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | empty | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 11/19/2021 | 6 inches above the mark | | | Spreading out of P1 as of F |
| P2 spread Pond | | 36 inches below | | | |
| P3 Corner Pond | | 1 inch above the mark | | | |
| P4 Irragation Pond | | 6 inches above the mark | | | |
| Dairy Storage | | 1 foot above the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | empty | | | |
| | | | | | |
| | | | | | |
| P1 Effluent | 12/6/2021 | 8 inches below the mark | | | |
| P2 spread Pond | | 24 inhes below the mark | | | |
| P3 Corner Pond | | 1 inch above the mark | | | |
| P4 Irragation Pond | | 6 inches above the mark | | | |
| Dairy Storage | | 6 inches above the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | empty | | | |
| | | | | | |
| P1 Effluent | 12/20/2021 | 30 inches below the mark | | | |
| P2 spread Pond | | 30 inches below the mark | | | |
| P3 Corner Pond | | 1 inch above the mark | | | |
| P4 Irragation Pond | | 6 inches above the mark | | | |
| Dairy Storage | | 30 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | empty | | | |
| | | | | | |
| P1 Effluent | 12/27/2021 | 30 inches below the mark | | | |
| P2 spread Pond | | 30 inches below the mark | | | |

| | | | | | |
|---|---|---|---|---|---|
| P3 Corner Pond | | 1 inch above the mark | | | |
| P4 Irragation Pond | | 6 inches above the mark | | | pumping p4 to p2 to sprea |
| Dairy Storage | | 30 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | empty | | | |
| | | | | | |
| P1 Effluent | 1/3/2022 | 30 inches below the mark | | | |
| P2 spread Pond | | on the mark | | | Kenny Spreading 1/4/2022 |
| P3 Corner Pond | | 1 inch above the mark | | | |
| P4 Irragation Pond | | 6 inches above the mark | | | |
| Dairy Storage | | 30 inches below the mark | | | |
| B4 Mix Tank | | 60 inches below the mark | | | |
| B1 Reception Pit | | 50 inches below the mark | | | |
| Heifer Storage | | empty | | | |

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

age

age

gets to mark

nce we have it lowered this week

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

rida, November 19th

| | | | |
|---|---|---|---|
| d | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

# EXPORT

2020

| DATE | Source | Export | Quantity |
| --- | --- | --- | --- |

| | | | |
|---|---|---|---|
| 2/14/2018 | P1 | Ch4 | 18000 |
| 2/15/2018 | P1 | CH4 | 6630.04 |

| | | | |
|---|---|---|---|
| 2/16/2018 | P1 | CH4 | 6300 |
| 2/19/2018 | P1 | CH4 | 18000 |
| 2/20/2018 | P1 | CH4 | 18000 |
| 2/21/2018 | P1 | Ch4 | 6867 |
| 2/21/2017 | P1 | Ch4 | 5421 |
| 2/21/2018 | P1 | Ch4 | 6867 |
| 2/22/2018 | P1 | Ch4 | 6090 |
| 2/23/2018 | P1 | Ch4 | 7282 |
| 2/23/2018 | P1 | Ch4 | 7844 |
| 2/23/2018 | P1 | Ch4 | 4749 |
| 2/26/2018 | P1 | Ch4 | 7612 |
| 2/26/2018 | P1 | Ch4 | 7257.63 |
| 2/28/2018 | P1 | Ch4 | 7775 |
| 3/6/2018 | P1 | Ch4 | 7000 |
| 3/6/2018 | P1 | Ch4 | 7000 |
| 3/7/2018 | P1 | Ch4 | 14000 |
| 3/8/2018 | P1 | Ch4 | 7000 |
| 3/8/2018 | P1 | Ch4 | 7000 |
| 3/9/2018 | P1 | Ch4 | 7000 |
| 3/9/2018 | P1 | Ch4 | 7000 |
| 3/10/2018 | P1 | Ch4 | 7447 |
| 3/10/2018 | P1 | Ch4 | 7310 |
| 3/11/2018 | P1 | Ch4 | 12000 |
| 3/11/2018 | P1 | Ch4 | 7000 |
| 3/11/2018 | P1 | Ch4 | 8400 |
| 3/11/2018 | P1 | Ch4 | 16000 |
| 3/12/2018 | P1 | Ch4 | 16000 |
| 3/13/2018 | Kan Pak | Ch4 | 8100 |
| 3/13/2018 | P1 | Ch4 | 7000 |
| 3/14/2018 | P1 | Ch4 | 7663 |
| 3/14/2018 | P1 | Ch4 | 8078 |
| 3/15/2018 | Kan Pak | Ch4 | 7500 |
| 3/15/2018 | P1 | Ch4 | 7349 |
| | | | 310541.67 |

| | | | | |
|---|---|---|---|---|
| 3/27/2018 | 12 | P1 | | 48,000 |
| 3/29/2018 | 2 | P1 | | 8,000 |
| 4/3/2018 | 10 | | P1 | 80000 |
| | | | | 136,000 |

136000
310541.67
446541.67

Thompson
Thompson
Thompson

| Date | Source | Type |
|---|---|---|
| 1/2/2021 | DFA | sludge |
| 1/4/2021 | DFA | sludge |
| 1/8/2021 | DFA | sludge |
| 1/11/2021 | DFA | sludge |
| 1/13/2021 | Dryden | sludge |
| 1/14/2021 | DFA | sludge |
| 1/15/2021 | DFA | wastewater |
| 1/16/2021 | DFA | wastewater |
| 1/18/2021 | DFA | wastewater |
| 1/20/2021 | DFA | sludge |
| 1/22/2021 | DFA | sludge |
| 2/8/2021 | DFA | sludge |
| 2/10/2021 | Leprino | wastewater |
| 2/12/2021 | Quest | wastewater |
| 2/17/2021 | Quest | wastewater |
| 2/19/2021 | Leprino | wastewater |
| 2/24/2021 | DFA | Sludge |
| 3/3/2021 | DFA | |
| 3/9/2021 | DFA | sludge |
| 3/11/2021 | Leprino | wastewater |
| 3/16/2021 | Leprino | wastewater |
| 3/18/2021 | Quest | wastewater |
| 3/22/2021 | Quest | wastewater |
| 3/24/2021 | DFA | wastewater |
| 4/5/2021 | Cayuga Hgts | sludge |
| 4/5/2021 | Canisteo | sludge |
| 4/5/2021 | Owego | sludge |
| 4/7/2021 | DFA | sludge |
| 4/7/2021 | Owego Town | sludge |
| 4/7/2021 | Watkins | sludge |
| 4/9/2021 | Cayuga Hgts | sludge |
| 4/9/2021 | Watkins | sludge |
| 4/9/2021 | Owego | sludge |
| 4/13/2021 | Owego | sludge |
| 4/14/2021 | Owego | sludge |
| 4/14/2021 | Owego | sludge |
| 4/20/2021 | Watkins | sludge |
| 4/20/2021 | Dryden | sludge |
| 4/22/2021 | Watkins | sludge |
| 4/22/2021 | Cayuga Hgts | sludge |
| 4/30/2021 | DFA | wastewater |
| 5/17/2021 | DFA | wastewater |
| 5/19/2021 | Leprino | |
| 5/21/2021 | Quest | wastewater |

| | | |
|---|---|---|
| 6/1/2021 | Waverly | sludge |
| 6/2/2021 | Cayuga Hgrs | sludge |
| 6/3/2021 | Quest | wastewater |
| 6/4/2021 | Perry | sludge |
| 6/4/2021 | Cayuga Hgts | sludge |
| 6/4/2021 | Quest | wastewater |
| 6/4/2021 | Perry | sludge |
| 6/4/2021 | Cayuga Hgts | sludge |
| 6/7/2021 | Watkins Glen | sludge |
| 6/11/2021 | Whitney Point | sludge |
| 6/15/2021 | Waverly | sludge |
| 6/15/2021 | DFA | sludge |
| 6/16/2021 | DFA | wastewater |
| 6/17/2021 | DFA | wastewater |
| 6/18/2021 | Cayuga Hgts | sludge |
| 6/21/2021 | Watkins Glen | sludge |
| 6/22/2021 | DFA | sludge |
| 6/23/2021 | Watkins Glen | sludge |
| 6/23/2021 | Perry | sludge |
| 6/24/2021 | DFA | wastewater |
| 6/24/2021 | Knoxville | sludge |
| 6/24/2021 | DFA | sludge |
| 6/25/2021 | DFA | wastewater |
| 6/25/2021 | Perry | sludge |
| 6/26/2021 | DFA | wastewater |
| 6/29/2021 | DFA | wastewater |
| 7/7/2021 | Quest | wastewater |
| 7/12/2021 | Waverly | sludge |
| 7/13/2021 | DFA | wastewater |
| 7/16/2021 | Canisteo | sludge |
| 7/22/2021 | DFA | wastewater |
| 7/26/2021 | Knoxville | sludge |
| 728/2021 | Perry | sludge |
| 8/8/2021 | Quest | waste water |
| 8/16/2021 | DFA | waste water |
| 8/19/2023 | DFA | waste water |
| 8/24/2021 | DFA | waste water |
| 8/31/2021 | Cayuga Heights | sludge |
| 9/1/2021 | Waverly | sludge |
| 9/2/2021 | Whitney Point | sludge |
| 9/3/2021 | Perry | sludge |
| 9/7/2021 | Watkins | sludge |
| 9/8/2021 | Quest | waste water |
| 9/14/2021 | cayuga heights | sludge |
| 9/15/2021 | Upstate | waste water from Floc Tank |
| 9/24/2021 | Quest | waste water |
| 9/27/2021 | Watkins | sludge |

| | | |
|---|---|---|
| 10/4/2021 | DFA | Waste Water |
| 10/6/2021 | Quest | Waste Water |
| 10/7/2021 | Waverly | Sludge |
| 10/14/2021 | Quest | waste water |
| 10/18/2021 | Quest | Waste Water |
| 10/20/2021 | DFA | Waste Water |
| 10/29/2021 | Quest | Waste Water |
| 11/3/2021 | DFA | Waste Water |
| 11/1/2021 | Kerry Bio Science | wastewater |
| 11/2/2021 | Watkins Glen | sludge |
| 11/2/2021 | Cayuga Hgts | sludge |
| 11/2/2021 | DFA | wastewater |
| 11/4/2021 | Waverly | sludge |
| 11/8/2021 | Cayuga Hgts | sludge |
| 11/9/2021 | Watkins Glen | sludge |
| 11/10/2021 | Cayuga Hgts | sludge |
| 11/17/2021 | Cayuga Hgts | sludge |
| 11/17/2021 | Watkins Glen | sludge |
| 11/18/2021 | Waverly | sludge |
| 11/23/2021 | DFA | wastewater |
| 11/23/2021 | DFA | wastewater |
| 12/17/2021 | DFA | wastewater |
| 12/18/2021 | DFA | wastewater |
| 12/1/2021 | Cayuga Hgts | sludge |
| 12/2/2021 | Waverly | sludge |
| 12/2/2021 | Perry | sludge |
| 12/6/2021 | Cayuga Hgts | sludge |
| 12/15/2021 | Waverly | sludge |
| 12/17/2021 | Watkins Glen | sludge |
| 12/17/2021 | DFA | Waste Water |
| 12/17/2021 | DFA | Waste Water |
| 12/21/2021 | Cayuga Hgts | sludge |
| 12/28/2021 | Waverly | sludge |
| | | |

| Tons | Gallons | Detination |
|---|---|---|
| 9 | | p2 |
| 6.29 | | p2 |
| 7.97 | | p2 |
| 14.17 | | P2 |
| 21.12 | | cement pad |
| 13.97 | | P2 |
| | 8,000.00 | P2 |
| | 16,300.00 | P2 |
| | 24,300.00 | P2 |
| 14.23 | | P2 |
| 12.87 | | P2 |
| 11.11 | | P2 |
| | 5,000.00 | p2 |
| | 7,000.00 | P2 |
| | 5,000.00 | p2 |
| | 2,500.00 | p2 |
| 12.58 | | P2 |
| 6.89 | | P2 |
| 16.43 | | P2 |
| | 5,000.00 | P2 |
| | 5,000.00 | p2 |
| | 5,500.00 | p2 |
| | 5,200.00 | p2 |
| | 5,500.00 | P2 |
| 15.9 | | cement pad |
| 17.79 | | cement pad |
| 20 | | cement pad |
| 15.54 | | p2 |
| 40 | | cement pad |
| 18.34 | | cement pad |
| 15.68 | | cement pad |
| 19.56 | | cement pad |
| 40 | | cement pad |
| 20 | | cement pad |
| 20 | | cement pad |
| 20 | | cement pad |
| 15.53 | | cement pad |
| 17.95 | | cement pad |
| 17.11 | | cement pad |
| 14.53 | | cement pad |
| | 30,000.00 | P2 |
| | 30,000.00 | P2 |
| | 1,500.00 | P2 |
| | 5,000.00 | P2 |

| | | |
|---|---|---|
| 16.6 | | cement pad |
| 15.16 | | cement pad |
| | 16,400.00 | p2 |
| 36.47 | | cement pad |
| 15.47 | | cement pad |
| | 4,200.00 | p2 |
| 36.47 | | cement pad |
| 15.47 | | cement pad |
| 17 | | cement pad |
| 17.97 | | cement pad |
| 17.95 | | cement pad |
| 15.68 | | p2 |
| | 6,300.00 | p2 |
| | 7,000.00 | p2 |
| 16.08 | | cement pad |
| 20.8 | | cement pad |
| 16.83 | | p2 |
| 19.95 | | Cement Pad |
| 20.97 | | cement pad |
| | 7,000.00 | p2 |
| 23.07 | | cement pad |
| 16.08 | | p2 |
| | 7,000.00 | p2 |
| 20.5 | | cement pad |
| | 7,000.00 | p2 |
| | 7000 | P2 |
| | 7000 | P2 |
| 18.07 | | cement pad |
| | 7,000.00 | P2 |
| 12.2 | | cement pad |
| | 6,250.00 | P2 |
| 12.2 | | cement pad |
| 13.8 | | cement pad |
| | 1,500.00 | P2 |
| | 7,000.00 | P2 |
| | 7,000.00 | P2 |
| | 7,000.00 | P2 |
| 15.17 | | cement pad |
| 18.97 | | cement pad |
| 18.87 | | cement pad |
| 18.1 | | cement pad |
| 17.1 | | cement pad |
| | 5,500.00 | p2 |
| 14.58 | | cement pad |
| | 2,500.00 | p2 |
| | 5,500.00 | p2 |
| 14.28 | | cement pad |

| | | |
|---|---|---|
| | 5,500.00 | P2 |
| | 5,000.00 | P2 |
| 12.28 | | cement pad |
| | 5,000.00 | P2 |
| | 4825.00 | P2 |
| | 5,500.00 | P2 |
| | 2,500.00 | P2 |
| | 7500.00 | P2 |
| | 5,500.00 | p2 |
| 18.7 | | cement pad |
| 16.76 | | cement pad |
| | 5,500.00 | p2 |
| 18.39 | | cement pad |
| 16.7 | | cement pad |
| 17.58 | | cement pad |
| 15.9 | | cement pad |
| 16.83 | | cement pad |
| 18.58 | | cement pad |
| 18.93 | | cement pad |
| | 3,770.00 | p2 |
| | 8,500.00 | p2 |
| | 19,264.00 | p2 |
| | 16,100.00 | p2 |
| 18.6 | | cement pad |
| 17.83 | | cement pad |
| 18.82 | | cement pad |
| 16 | | cement pad |
| 17.1 | | cement pad |
| 16.82 | | cement pad |
| | 6850.00 | p2 |
| | 5987.00 | P2 |
| 17.5 | | cement pad |
| 20.07 | | cement pad |
| | | |