

Storage Inspection					
2020	Date	Level	Initials	Condition	Corrective Action
	1/4/2021	6 inches below the mark			
P1 Effluent		on the mark			
P2 spread Pond		13 inches below the mark			
P3 Corner Pond		14 inches below the mark			
P4 Irragation Pond		48 inches below the mark			
Dairy Storage		60 inches below the mark			
B4 Mix Tank		50 inches below the mark			
B1 Reception Pit		60 inches below the mark			
Heifer Storage					
	1/11/2021	6 inches inches below the mark			
P1 Effluent		on the mark			
P2 spread Pond		13 inches below the mark			
P3 Corner Pond		14 inches below the mark			
P4 Irragation Pond		48 inches below the mark			
Dairy Storage		60 inches below the mark			
B4 Mix Tank		50 inches below the mark			
B1 Reception Pit		60 inches below the mark			
Heifer Storage					
	1/18/2021	6 inches inches below the mark			
P1 Effluent		on the mark			
P2 spread Pond		13 inches below the mark			
P3 Corner Pond		14 inches below the mark			
P4 Irragation Pond		48 inches below the mark			
Dairy Storage		60 inches below the mark			
B4 Mix Tank		50 inches below the mark			
B1 Reception Pit		60 inches below the mark			
Heifer Storage					
	1/25/2021	6 inches inches below the mark			
P1 Effluent		on the mark			
P2 spread Pond		13 inches below the mark			
P3 Corner Pond		14 inches below the mark			
P4 Irragation Pond		48 inches below the mark			
Dairy Storage		60 inches below the mark			
B4 Mix Tank		50 inches below the mark			
B1 Reception Pit		60 inches below the mark			
Heifer Storage					
	2/1/2021	6 inches inches below the mark			
P1 Effluent		on the mark			
P2 spread Pond		13 inches below the mark			
P3 Corner Pond		14 inches below the mark			
P4 Irragation Pond		48 inches below the mark			
Dairy Storage		60 inches below the mark			
B4 Mix Tank					

B1 Reception Pit		50 inches below the mark	
Heifer Storage		60 inches below the mark	
P1 Effluent	2/8/2021	6 inches inches below the mark	
P2 spread Pond		on the mark	
P3 Corner Pond		13 inches below the mark	
P4 Irragation Pond		14 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		60 inches below the mark	
P1 Effluent	2/15/2021	6 inches inches below the mark	
P2 spread Pond		on the mark	
P3 Corner Pond		13 inches below the mark	
P4 Irragation Pond		14 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		60 inches below the mark	
P1 Effluent	2/22/2021	6 inches inches below the mark	
P2 spread Pond		on the mark	
P3 Corner Pond		13 inches below the mark	
P4 Irragation Pond		14 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		60 inches below the mark	
P1 Effluent	3/1/2021	6 inches inches below the mark	
P2 spread Pond		on the mark	
P3 Corner Pond		13 inches below the mark	
P4 Irragation Pond		14 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		60 inches below the mark	
P1 Effluent	3/8/2021	6 inches inches below the mark	
P2 spread Pond		on the mark	
P3 Corner Pond		13 inches below the mark	
P4 Irragation Pond		14 inches below the mark	

Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		60 inches below the mark	
P1 Effluent	3/15/2021	6 inches inches below the mark	
P2 spread Pond		on the mark	pumping P2 into P3
P3 Corner Pond		13 inches below the mark	
P4 Irragation Pond		14 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		6 inches above the mark	spreading out of dairy stor
P1 Effluent	3/22/2021	6 inches inches below the mark	
P2 spread Pond		4 inches below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irragation Pond		10 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		4 inches above the mark	spreading out of dairy stor
P1 Effluent	3/29/2021	6 inches inches below the mark	
P2 spread Pond		4 inches below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irragation Pond		10 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	4/5/2021	6 inches inches below the mark	
P2 spread Pond		5 inches below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irragation Pond		10 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	4/12/2021	6 inches inches below the mark	
P2 spread Pond		5 inches below the mark	

P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		10 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	4/19/2021	6 inches inches below the mark	
P2 spread Pond		5 inches below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		10 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	4/26/2021	6 inches inches below the mark	
P2 spread Pond		5 inches below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		10 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	5/3/2021	6 inches inches below the mark	
P2 spread Pond		5 inches below the mark	pumping P4 into P2 until it
P3 Corner Pond		10 inches below the mark	pumping P3 to P4
P4 Irrigation Pond		10 inches below the mark	pumping P4 to P2
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	5/10/2021	6 inches inches below the mark	
P2 spread Pond		5 inches below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		10 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	5/17/2021	6 inches inches below the mark	
P2 spread Pond		5 inches below the mark	

P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		on the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	5/24/2021	6 inches inches below the mark	
P2 spread Pond		on the mark	spreading out of P2
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		on the mark	p4 will be pumped to P2 or
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	6/1/2021	6 inches inches below the mark	
P2 spread Pond		1 inch below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		on the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	6/7/2021	6 inches inches below the mark	
P2 spread Pond		5 inch below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		on the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	6/14/2021	6 inches inches below the mark	
P2 spread Pond		6 inch below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		on the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	6/21/2021	6 inches inches below the mark	
P2 spread Pond		26 inch below the mark	
P3 Corner Pond		10 inches below the mark	

P4 Irrigation Pond		12 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	6/28/2021	6 inches inches below the mark	
P2 spread Pond		26 inch below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		12 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	7/5/2021	6 inches inches below the mark	
P2 spread Pond		26 inch below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		12 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	7/12/2021	6 inches inches below the mark	
P2 spread Pond		26 inch below the mark	
P3 Corner Pond		10 inches below the mark	
P4 Irrigation Pond		12 inches below the mark	
Dairy Storage		48 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	7/19/2021	on the mark	
P2 spread Pond		on the mark	
P3 Corner Pond		3 inches below the mark	
P4 Irrigation Pond		on the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	7/26/2021	on the mark	
P2 spread Pond		on the mark	

P3 Corner Pond		3 inches below the mark	
P4 Irrigation Pond		on the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	8/2/2021	above the mark	
P2 spread Pond		above the mark	
P3 Corner Pond		above the mark	
P4 Irrigation Pond		above the mark	
Dairy Storage		above the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	8/9/2021	above the mark	
P2 spread Pond		above the mark	
P3 Corner Pond		above the mark	
P4 Irrigation Pond		above the mark	
Dairy Storage		above the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	8/16/2021	6 inches below the mark	
P2 spread Pond		on the mark 8/17/2021 3pm	
P3 Corner Pond		above the mark	
P4 Irrigation Pond		on the mark	
Dairy Storage		above the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	8/23/2021	1 inch below the mark	
P2 spread Pond		on the mark	
P3 Corner Pond		above the mark	
P4 Irrigation Pond		on the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	8/30/2021	12 inches below the mark	
P2 spread Pond		12 inches below the mark	
P3 Corner Pond		above the mark	

P4 Irrigation Pond		3 inches below the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	9/7/2021	12 inches below the mark	
P2 spread Pond		12 inches below the mark	
P3 Corner Pond		above the mark	
P4 Irrigation Pond		3 inches below the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	9/13/2021	12 inches below the mark	
P2 spread Pond		12 inches below the mark	
P3 Corner Pond		above the mark	
P4 Irrigation Pond		3 inches below the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	9/20/2021	12 inches below the mark	
P2 spread Pond		12 inches below the mark	
P3 Corner Pond		above the mark	
P4 Irrigation Pond		3 inches below the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	9/27/2021	12 inches below the mark	
P2 spread Pond		12 inches below the mark	
P3 Corner Pond		above the mark	
P4 Irrigation Pond		3 inches below the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	10/4/2021	12 inches below the mark	
P2 spread Pond		12 inches below the mark	
P3 Corner Pond		above the mark	

P4 Irrigation Pond		3 inches below the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	10/12/2021	on the mark	
P2 spread Pond		on the mark	
P3 Corner Pond		on the mark	
P4 Irrigation Pond		3 inches below the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	10/18/2021	on the mark	
P2 spread Pond		2 inches below the mark	
P3 Corner Pond		on the mark	
P4 Irrigation Pond		3 inches below the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	10/25/2021	on the mark	
P2 spread Pond		on the mark	
P3 Corner Pond		on the mark	
P4 Irrigation Pond		on the mark	
Dairy Storage		on the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		40 inches below the mark	
P1 Effluent	11/1/2021	full	
P2 spread Pond		full	
P3 Corner Pond		full	
P4 Irrigation Pond		full	
Dairy Storage		full	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		empty	
P1 Effluent	11/8/2021	6 inches above the mark	
P2 spread Pond		6 inches above the mark	
P3 Corner Pond		6 inches above the mark	
P4 Irrigation Pond		6 inches above the mark	

Dairy Storage		1 foot above the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		empty	
P1 Effluent	11/15/2021	6 inches above the mark	
P2 spread Pond		20 inches below the mark	
P3 Corner Pond		3 inches above the mark	
P4 Irrigation Pond		6 inches above the mark	
Dairy Storage		1 foot above the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		empty	
P1 Effluent	11/19/2021	6 inches above the mark	Spreading out of P1 as of F
P2 spread Pond		36 inches below	
P3 Corner Pond		1 inch above the mark	
P4 Irrigation Pond		6 inches above the mark	
Dairy Storage		1 foot above the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		empty	
P1 Effluent	12/6/2021	8 inches below the mark	
P2 spread Pond		24 inches below the mark	
P3 Corner Pond		1 inch above the mark	
P4 Irrigation Pond		6 inches above the mark	
Dairy Storage		6 inches above the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		empty	
P1 Effluent	12/20/2021	30 inches below the mark	
P2 spread Pond		30 inches below the mark	
P3 Corner Pond		1 inch above the mark	
P4 Irrigation Pond		6 inches above the mark	
Dairy Storage		30 inches below the mark	
B4 Mix Tank		60 inches below the mark	
B1 Reception Pit		50 inches below the mark	
Heifer Storage		empty	
P1 Effluent	12/27/2021	30 inches below the mark	
P2 spread Pond		30 inches below the mark	

EXPORT

2020

DATE	Source	Export	Quantity
------	--------	--------	----------

2/14/2018	P1	Ch4	18000
2/15/2018	P1	CH4	6630.04

2/16/2018	P1	CH4	6300
2/19/2018	P1	CH4	18000
2/20/2018	P1	CH4	18000
2/21/2018	P1	Ch4	6867
2/21/2017	P1	Ch4	5421
2/21/2018	P1	Ch4	6867
2/22/2018	P1	Ch4	6090
2/23/2018	P1	Ch4	7282
2/23/2018	P1	Ch4	7844
2/23/2018	P1	Ch4	4749
2/26/2018	P1	Ch4	7612
2/26/2018	P1	Ch4	7257.63
2/28/2018	P1	Ch4	7775
3/6/2018	P1	Ch4	7000
3/6/2018	P1	Ch4	7000
3/7/2018	P1	Ch4	14000
3/8/2018	P1	Ch4	7000
3/8/2018	P1	Ch4	7000
3/9/2018	P1	Ch4	7000
3/9/2018	P1	Ch4	7000
3/10/2018	P1	Ch4	7447
3/10/2018	P1	Ch4	7310
3/11/2018	P1	Ch4	12000
3/11/2018	P1	Ch4	7000
3/11/2018	P1	Ch4	8400
3/11/2018	P1	Ch4	16000
3/12/2018	P1	Ch4	16000
3/13/2018	Kan Pak	Ch4	8100
3/13/2018	P1	Ch4	7000
3/14/2018	P1	Ch4	7663
3/14/2018	P1	Ch4	8078
3/15/2018	Kan Pak	Ch4	7500
3/15/2018	P1	Ch4	7349
			310541.67

3/27/2018	12	P1		48,000
3/29/2018	2	P1		8,000
4/3/2018	10		P1	80000
				136,000

136000
310541.67
446541.67

Thompson
Thompson
Thompson

Date	Source	Type	Tons	Gallons	Detination	Date	Field
1/2/2021	DFA	sludge	9		p2		
1/4/2021	DFA	sludge	6.29		p2		
1/8/2021	DFA	sludge	7.97		p2		
1/11/2021	DFA	sludge	14.17		P2		
1/13/2021	Dryden	sludge	21.12		cement pad	3/10/2021	N1
1/14/2021	DFA	sludge	13.97		P2		
1/15/2021	DFA	wastewater		8,000.00	P2		
1/16/2021	DFA	wastewater		16,300.00	P2		
1/18/2021	DFA	wastewater		24,300.00	P2		
1/20/2021	DFA	sludge	14.23		P2		
1/22/2021	DFA	sludge	12.87		P2		
2/8/2021	DFA	sludge	11.11		P2		
2/10/2021	Leprino	wastewater		5,000.00	p2		
2/12/2021	Quest	wastewater		7,000.00	P2		
2/17/2021	Quest	wastewater		5,000.00	p2		
2/19/2021	Leprino	wastewater		2,500.00	p2		
2/24/2021	DFA	Sludge	12.58		P2		
3/3/2021	DFA		6.89		P2		
3/9/2021	DFA	sludge	16.43		P2		
3/11/2021	Leprino	wastewater		5,000.00	P2		
3/16/2021	Leprino	wastewater		5,000.00	p2		
3/18/2021	Quest	wastewater		5,500.00	p2		
3/22/2021	Quest	wastewater		5,200.00	p2		
3/24/2021	DFA	wastewater		5,500.00	P2		
4/5/2021	Cayuga Hgts	sludge	15.9		cement pad	3/10/2021	N1
4/5/2021	Canisteo	sludge	17.79		cement pad	4/5/2021	St5
4/5/2021	Owego	sludge	20		cement pad	4/5/2021	St5
4/7/2021	DFA	sludge	15.54		p2		
4/7/2021	Owego Town	sludge	40		cement pad	4/7/2021	St6
4/7/2021	Watkins	sludge	18.34		cement pad	4/7/2021	St6
4/9/2021	Cayuga Hgts	sludge	15.68		cement pad	4/9/2021	ST7
4/9/2021	Watkins	sludge	19.56		cement pad	4/9/2021	ST7
4/9/2021	Owego	sludge	40		cement pad	4/9/2021	St4
4/13/2021	Owego	sludge	20		cement pad	4/14/2022	St4
4/14/2021	Owego	sludge	20		cement pad	4/14/2022	St5
4/14/2021	Owego	sludge	20		cement pad	4/14/2022	St6
4/20/2021	Watkins	sludge	15.53		cement pad	5/26/2021	St5
4/20/2021	Dryden	sludge	17.95		cement pad	5/26/2021	St5
4/22/2021	Watkins	sludge	17.11		cement pad	5/27/2021	St6
4/22/2021	Cayuga Hgts	sludge	14.53		cement pad	5/27/2021	St6
4/30/2021	DFA	wastewater		30,000.00	P2		
5/17/2021	DFA	wastewater		30,000.00	P2		
5/19/2021	Leprino			1,500.00	P2		
5/21/2021	Quest	wastewater		5,000.00	P2		
6/1/2021	Waverly	sludge	16.6		cement pad	17-Jun	St4
6/2/2021	Cayuga Hgrs	sludge	15.16		cement pad	17-Jun	St4
6/3/2021	Quest	wastewater		16,400.00	p2		
6/4/2021	Perry	sludge	36.47		cement pad	17-Jun	St4
6/4/2021	Cayuga Hgts	sludge	15.47		cement pad	17-Jun	St4
6/4/2021	Quest	wastewater		4,200.00	p2		
6/4/2021	Perry	sludge	36.47		cement pad	19-Jun	St5
6/4/2021	Cayuga Hgts	sludge	15.47		cement pad	19-Jun	ST5
6/7/2021	Watkins Glen	sludge	17		cement pad	19-Jun	St6
6/11/2021	Whitney Point	sludge	17.97		cement pad	19-Jun	St6
6/15/2021	Waverly	sludge	17.95		cement pad	29-Jun	St7
6/15/2021	DFA	sludge	15.68		p2		
6/16/2021	DFA	wastewater		6,300.00	p2		
6/17/2021	DFA	wastewater		7,000.00	p2		
6/18/2021	Cayuga Hgts	sludge	16.08		cement pad	29-Jun	St7
6/21/2021	Watkins Glen	sludge	20.8		cement pad	29-Jun	St7
6/22/2021	DFA	sludge	16.83		p2		
6/23/2021	Watkins Glen	sludge	19.95		Cement Pad	29-Jun	St4
6/23/2021	Perry	sludge	20.97		cement pad	29-Jun	St5
6/24/2021	DFA	wastewater		7,000.00	p2		
6/24/2021	Knoxville	sludge	23.07		cement pad	29-Jun	St6
6/24/2021	DFA	sludge	16.08		p2		
6/25/2021	DFA	wastewater		7,000.00	p2		
6/25/2021	Perry	sludge	20.5		cement pad	8/5/2021	P1A
6/26/2021	DFA	wastewater		7,000.00	p2		
6/29/2021	DFA	wastewater		7000	P2		
7/7/2021	Quest	wastewater		7000	P2		
7/12/2021	Waverly	sludge	18.07		cement pad	8/6/2021	P1A
7/13/2021	DFA	wastewater		7,000.00	P2		
7/16/2021	Canisteo	sludge	12.2		cement pad	8/6/2021	P1A
7/22/2021	DFA	wastewater		6,250.00	P2		
7/26/2021	Knoxville	sludge	12.2		cement pad	8/7/2021	P1A
728/2021	Perry	sludge	13.8		cement pad	8/7/2021	P1A
8/8/2021	Quest	waste water		1,500.00	P2		
8/16/2021	DFA	waste water		7,000.00	P2		
8/19/2023	DFA	waste water		7,000.00	P2		
8/24/2021	DFA	waste water		7,000.00	P2		

8/31/2021	Cayuga Heights	sludge	15.17		cement pad	13-Oct	M5
9/1/2021	Waverly	sludge	18.97		cement pad	13-Oct	M5
9/2/2021	Whitney Point	sludge	18.87		cement pad	14-Oct	M5
9/3/2021	Perry	sludge	18.1		cement pad	14-Oct	M5
9/7/2021	Watkins	sludge	17.1		cement pad	15-Oct	M5
9/8/2021	Quest	waste water		5,500.00	p2		
9/14/2021	cayuga heights	sludge	14.58		cement pad	15-Oct	M5
9/15/2021	Upstate	waste water from Floc Tank		2,500.00	p2		
9/24/2021	Quest	waste water		5,500.00	p2		
9/27/2021	Watkins	sludge	14.28		cement pad	15-Oct	M5
10/4/2021	DFA	Waste Water		5,500.00	P2		
10/6/2021	Quest	Waste Water		5,000.00	P2		
10/7/2021	Waverly	Sludge	12.28		cement pad	11-Nov	M2
10/14/2021	Quest	waste water		5,000.00	P2		
10/18/2021	Quest	Waste Water		4825.00	P2		
10/20/2021	DFA	Waste Water		5,500.00	P2		
10/29/2021	Quest	Waste Water		2,500.00	P2		
11/3/2021	DFA	Waste Water		7500.00	P2		
11/1/2021	Kerry Bio Science	wastewater		5,500.00	p2		
11/2/2021	Watkins Glen	sludge	18.7		cement pad	11-Nov	M2
11/2/2021	Cayuga Hgts	sludge	16.76		cement pad	11-Nov	M3
11/2/2021	DFA	wastewater		5,500.00	p2		
11/4/2021	Waverly	sludge	18.39		cement pad	14-Nov	M3
11/8/2021	Cayuga Hgts	sludge	16.7		cement pad	14-Nov	H3
11/9/2021	Watkins Glen	sludge	17.58		cement pad	15-Nov	H3
11/10/2021	Cayuga Hgts	sludge	15.9		cement pad	15-Nov	P1A
11/17/2021	Cayuga Hgts	sludge	16.83		cement pad	17-Nov	P1A
11/17/2021	Watkins Glen	sludge	18.58		cement pad	17-Nov	H3
11/18/2021	Waverly	sludge	18.93		cement pad	18-Nov	H3
11/23/2021	DFA	wastewater		3,770.00	p2		
11/23/2021	DFA	wastewater		8,500.00	p2		
12/17/2021	DFA	wastewater		19,264.00	p2		
12/18/2021	DFA	wastewater		16,100.00	p2		
12/1/2021	Cayuga Hgts	sludge	18.6		cement pad	6-Dec	A12S
12/2/2021	Waverly	sludge	17.83		cement pad	6-Dec	A12S
12/2/2021	Perry	sludge	18.82		cement pad	6-Dec	A12S
12/6/2021	Cayuga Hgts	sludge	16		cement pad	6-Dec	A12S
12/15/2021	Waverly	sludge	17.1		cement pad	17-Dec	A12S
12/17/2021	Watkins Glen	sludge	16.82		cement pad	17-Dec	A12S
12/17/2021	DFA	Waste Water		6850.00	p2		
12/17/2021	DFA	Waste Water		5987.00	P2		
12/21/2021	Cayuga Hgts	sludge	17.5		cement pad	28-Dec	A12S
12/28/2021	Waverly	sludge	20.07		cement pad	28-Dec	A12S
1/7/2022	Cayuga Heights	sludge	17.52		cement pad	remains on pad	1/11/2022
1/5/2022	Cayuga Heights	sludge	16		cement pad	remains on pad	1/11/2022
1/5/2022	Watkins	sludge	19.1		cement pad	remains on pad	1/11/2022